

BALKAMP

BKN - Warranty Code 504 – 12 Months or 12,000 Miles whichever occurs first

REMANUFACTURED CARBURETORS

Limitations: NAPA Remanufactured Carburetors does **NOT** warranty the proper or improper installation and/or application of the purchase, exchange, trade, bartered, or complimentary installer. NAPA Remanufactured Carburetors assumes no liability and will not pay for labor, damage, rental car, hotel, towing claims, etc., arising from the installation or use of the above mentioned carburetor(s). Also due to the complexity of emission control systems, NAPA Remanufactured Carburetors does not warranty the carburetor(s) to pass emission control inspections solely on its own merit. This guarantee does not apply to any defects caused by misuse, collisions or other accidents, negligence, or any unauthorized or unreasonable use including, but not limited to, improper application and installation.

NAPA Remanufactured Carburetors neither assumes nor authorized any person, agent, distributor, dealer, repair technician, service facility, or company to change, modify, supplement or amend this warranty or assume for NAPA Remanufactured Carburetors any warranty or liability in connections with the remanufacturing, sale, shipment, or use of our products. NAPA Remanufactured Carburetors does not authorize any other person, agent, distributor, dealer, repair technician, service facility or company to make any qualitative determination as to the fitness of our products.

NAPA Remanufactured Carburetors reserves the right to make changes, modifications or improvements in our products without incurring any obligation to similarly alter, modify or improve products previously purchased, exchanged, traded, bartered or complementary procured.

CONDITIONS OF WARRANTIES

NAPA Remanufactured Carburetors is proud to offer high quality products at a low price. We do not sell carburetor(s) for testing purposes. All NAPA Remanufactured Carburetors are live engine tested or flow tested to assure performance.

1. All Carburetor(s) must be returned to NAPA Remanufactured Carburetors for warranty work. No exchanges, refunds or credits at any time.
2. Carburetors will only be repaired and/or retested under warranty with the approval from NAPA Remanufactured Carburetors Technical Assistance Department. The customer must first call Technical Assistance with any problems before removing carburetor(s). A RGA number will be required to return the product to NAPA Remanufactured Carburetors for warranty work.
3. Purchaser must present original sales receipt and box must be clearly marked with RGA number before any warranty work will be performed.
4. Any temper seal found to be broken will automatically void guarantee.
5. Any returned carburetor(s) found to be contaminated with rust, varnish or any other type of contaminant will automatically void guarantee.

CORE RETURN POLICY

THE FOLLOWING CONDITIONS MUST BE MET TO RECEIVE CORE CREDIT

1. Core must be returned in original box of purchase
2. Core must be packaged and wrapped to avoid damage
3. Core must be returned within 90 days
4. Core must have all original parts attached
5. Core must be re-buildable and free of broken parts
6. Core must be exact unit sold
7. Core from salvage yard or with water damage will not be accepted
8. Copy of original invoice must be included with core

NO CREDIT ON THE FOLLOWING

- Frozen Bases
- Broken Castings
- Disassembled Cores
- Non-Matching Cores

****CORES WILL BE INSPECTED AND RETURNED IF UNACCEPTABLE****