



1 Sierra Place  
Litchfield IL 62056-3029

DATE: 06/21/18

BULLETIN NO. PL-18-PU-003

TO: ALL PRIME LINE CUSTOMERS AND SALES PROFESSIONALS

SUBJECT: VP SPORTSMAN CONTAINER WARRANTY PROCEDURE

Prime Line Sierra will require the attached warranty claim to be completed when filing for warranty due to a defect on all VP Sportsman Containers. Please contact Technical Service at 800-648-3976 option 3 for an RGA #. Once RGA # is obtained send the completed warranty form along with alleged defective product to:

Sierra International  
1 Sierra Place  
Litchfield, IL 62056

**(RGA # must be clearly marked on the outside of package that is to be returned)**

If you receive a VP Sportsman Container that is missing the following items, fill hose / cap / vent cap please contact Technical Service for replacement item(s).

Part No.	Description
3516	Sportsman Container w/hose, 5 Gal. (RED)
3520	Sportsman Container w/hose, 5 Gal. (WHITE)
3536	Sportsman Container w/hose, 5 Gal. (BLUE)
3556	Sportsman Container w/hose, 5 Gal. (YELLOW)
3846	Sportsman Container w/hose, 5 Gal. (CAMO GREEN)



Thank you for your continued support.

Regards,

Walter Rieck  
National Sales & Training Manager



**MAKIN' POWER!**  
VPRacingFuels.com



**PRODUCT WARRANTY CLAIM FORM  
MOTORSPORT CONTAINER® AND SPORTSMAN'S CONTAINER®  
MANUFACTURED BY PLASTIC PRODUCT FORMERS, INC.**



**DESCRIBE THE ISSUE YOU ARE EXPERIENCING WITH THIS PRODUCT:**

**FOR PRODUCT REPLACEMENT CONSIDERATION - PROVIDE THE FOLLOWING INFORMATION:**

NAME: \_\_\_\_\_

ADDRESS & PHONE NUMBER: \_\_\_\_\_

STORE PURCHASED AT: \_\_\_\_\_

PRICE PAID: \$ \_\_\_\_\_

Date of Purchase: \_\_\_\_\_